







THE GCDuino² PINOUT DIAGRAM




Programmer Connection


-  Components face up When plugged in
-  Uses Serial Rx & Tx Pins


LEGEND


Ground
Power
Port Address
Digital Pin
Analog Pin
Pin Change INT
Communication
Control
Pin Function
PWM
Special


-  IMPORTANT
-  INFORMATION



 SS Must be an OUTPUT to use the SPI bus

 SPI bus is the MOSI, MISO & SCK Pins

 Serial is the Rx & Tx Pins

 I2C bus is the SCL & SDA Pins

